# Auto-Measurement by MPI Probe Station with SENTIO<sup>®</sup> Software Suite in NoiseProPlus<sup>™</sup>

NoiseProPlus<sup>TM</sup> can control MPI semi-auto probe station (e.g. TS3000-SE) with SENTIO<sup>®</sup> Software suite V2.8.0 to measure the 1/f noise automatically. The procedure for auto-measurement is described in this document. The following general steps are followed in a typical 1/f noise measurement setup using NoiseProPlus<sup>TM</sup>.

# Load Wafer on the Probe Station

To load a wafer on the probe station correctly, you need to get more detailed information from the user's manual of MPI TS3000-SE probe station series. Listed below are some general guidelines:

- (1). Move the chuck to load position.
- (2). Remove vacuum.
- (3). Put a wafer on chuck.
- (4). Add vacuum.
- (5). Align wafer to alignment position.
- (6). Create a wafer map for die and subdie to measure by using wafer map editor.
- (7). Make sure the chuck can move to the correct position of die and sub-die using this wafer map at alignment height.

General Information Setup	×
User Name Zhl Lot Name Sample Lot <sup>3</sup> Device ID CLN28HQ	Device Type MOSFET  Date Created 2/14/2013 Temp. (°C) 27
Any comment typed here will be setup file and Noise Data Files.	recorded into the NoisePro
File Name C:\NoisePro\temp\n	mos.noi
<u>0</u> K	<u>C</u> ancel

Figure 1. General Information setup

# Configure a New Device on NoiseProPlus<sup>™</sup> Software

Device Setup					×
MOSFET					
Tox (Å)	100	Nrd	0	Sa(um)	
≍j (um)	.1	Nrs	0	Sb(um)	
Drawn L (um)	1	Ad (um*um)	0	Sd(um)	
Drawn W (um)	24	As (um*um)	0	min	
Delta L (um)	0	Pd (um)	0	sca	
Delta W (um)	0	Ps (um)	0	scb	
m	1	nf	1	SCC	
( NMOS (	○ PMOS	nfin		sc(um)	
<u>0</u>	<	Cancel			More items

To configure a new device to be measured, launch the NoiseProPlus<sup>TM</sup> software and select the appropriate device type from the toolbar menu **Setup**  $\rightarrow$  **General Information Setup** as shown in fig. 1 above. We will use a NMOS device in this application note. Next click on **Setup**  $\rightarrow$  **Device Information** to fill out instance parameters as needed as shown in fig. 2 below.

Figure 2. Device Information setup

## Setup the IV Meter, Spectrum Analyzer and Noise Analyzer

To setup each of the hardware items, click on the toolbar menu **Setup** → **Measurement Setup** and browse through each tab to configure items such as IV meter, Spectrum Analyzer and Noise Analyzer shown below in fig. 3.

/ Meter		IT Mode	Channel Propert						
IV Model :				Drain:	Gate:	Source:	Bulk:		
IV Model:	HP81500 💌	<ul> <li>Short</li> </ul>	ADC type	HR	HR	HR	HR		
			Filter	OFF	OFF	OFF	OFF		
GPIB Address :	GPIB Address : 17 C Medium		I meas. range(A)	1e-9	1e-9	1e-9	1e-9		
, , , , , , , , , , , , , , , , , , , ,		V meas. range(V)	20	20	20 20 20				
MUs & Nodes			General Property	y					
SMU	Enable V-Mode/I-Mo	de Compliance			Value	Value			
Drain: ch#1 • V-Mode • .1 (A)		▼1 (A)	Hold Time						
		Delay Time	0	0					
Gate: ch#2 • V-Mode •	▼ .1 (A)	Average	Average			1			
. –			Meas. Wait coeffic	ient	1				
Source: ch#3	V-Mode	▼ .1 (A)	Meas. Wait offset(	\$]	0				
			Output Wait coeffi	cient	1				
Bulk: ch#4	V-Mode	• .1 (A)	Output Wait offset	-	0				
			Range Rate		50				
Max. SMU Output	(V) 20	Initialize	ADC operation mo	de	PLC				
			WM Final Value		Start_va	alue			

Figure 3. Measurement setup

### Setup Probe Station

To setup the probe station, click on menu **Setup** → **Measurement Setup** → **Prober Setup**. Enable the **Use Prober** option (if disabled) and select **MPI with GPIB** (emulator mode) from the Prober Model. Set the correct GPIB address and click **Start** to test the connection between software and prober as shown in fig. 4 below. Note there is no need to specify the MPI Prober Driver Path (grayed out) when controlling the probe station in emulator mode. It is also important to note that SENTIO<sup>®</sup> software suite is capable of interpreting Cascade Nucleus commands.

ation -																
lodel:		MF	MPI with GPIB  GPIB Address: 13 Time Out : 1000 Star								Start					
river P.	ath:	C:\	Voisepro/N	oiseCon										1		
Joy Lo	ck Dur	ing Meas	urement											_		
		1	D:\NoiseProT\wafermap.xwmf													
ected [	Device	File:														
ormal	ion S	etup													Load	
													Sa	Sb	Sd	Rdc
100	0.1		24	ų	0 -1000	1000	-1000	-1000	·1000	-1000	-1	+1000	1000	-1000	-1000	-1000
																>
	ormat															
		_	oisePro\Noi	seCom									_			1
and Fe Data	Path	IC:\N	Save as noi     C Save as csv     C Save as noi and csv								1					
		,			C Sa	ve as .cs	/		C Sav	e as .no	i and	LCSV				
	oriver P Joy Lor ap File ected [ format	rriver Path: Joy Lock Dur p ap File: ected Device formation S Tox Xi I 100 0.1	iniver Path: C:\\     Joy Lock During Measurement     p     ap File: D:\\     cected Device File:     formation Setup     Tox Xi DrawnL     1000 0.1 1	Periver Derive Path: CVNoseproV Joy Lock During Measurement     P     P     P     File:     D:WoiseProTV     ected Device File:     formation Setup     Tox: X_D Drawn. DrawnW     Tox V     Tox V     D     T     24	In the second se	Implementation         Display         Display <thdisplay< th="">         Display         <thdisplay< th=""></thdisplay<></thdisplay<>	Interview Park         C: Wasseport Notes Com           1oy Lock During Measurement         P           ps File:         D: WolderProT Wastermap.xvmf           ected Device File:         Image: Comparison of the protocol of the p	Interview UP         Display           Interview Dets         C::WaseproVNotecCom           1oy Lock During Measurement         P           PF //r.         D::WoldeProTWastemap.xvml           ected Device File         Interview View DL           formation Setup         Interview Display           Text         JD. Itawerk/           Dig 0         1           24         0           0         1:000	per ven um Um         per ven um         pe ven um         per ven um         per ven um<	Interf with Orbits         Distribution         Distrib	Interview of the second seco	Interview with UP and the second se	perform with UPD         Distribution         [13]         Distribution         [10]           1oy Lock During Measurement         p         File         D: MoisePro T Wademap, xwml         excited Device File           formation Setup         Text MD         Distribution         MRD         MRS         AD         AS         PO         PS         m         nf         nf         f <td>prime with with of the part of</td> <td>Imministration Parks        </td> <td>Implementation         Divide Point        </td>	prime with with of the part of	Imministration Parks	Implementation         Divide Point

Figure 4. Prober setup

Next load the wafer map in SENTIO<sup>®</sup> as shown in fig. 5 below. User may manually select the dies to be tested and export the wafer map to the desktop or import an exsiting wafer map file with a .trex extension. Browse for the **Wafer map file** copied from the probe station computer to the location accessible by the NoiseProPlus<sup>™</sup> if SEN-TIO<sup>®</sup> and NoiseProPlus<sup>™</sup> are installed on different machines. Note this step is optional since NoiseProPlus<sup>™</sup> can automatically move the prober from die to die when the wafer map file is loaded on the probe station. In order to complete the prober setup, device information setup needs to be loaded by clicking the **Load** button after having filled the necessary DUT details as shown in fig. 4 above. NoiseProPlus<sup>™</sup> automatically saves the noise data to a default temp path which can be edited by the user to a specific location alongwith the desired noise data format. Die and sub-die information can be embedded in the saved data filename by clicking on the appropriate option under **Data Path and Format**. Once the setup configuration is complete, hit **Apply** then **OK** to load the full setup in the device tab.




Figure 5: SENTIO® Software Suite: Wafer map setup (GPIB)

### Auto-Measurement

NoiseProPlus<sup>™</sup> automatically understands the setup as auto-measurement when the **Use prober** is enabled and multiples dies (and/or sub-dies) are selected on the wafer map in the emulator mode described above. Now from the menu, select **Measure** → **Measure Noise** and a new window **Sid Spectrum DSA channel:1** window appears, select **Measure** → **Measure 1/f Noise** to start the measurement. User may also select **Measure** → **Measure 1/f Noise for Multi-Device** in the measurement window. NoiseProPlus<sup>™</sup> will then load an auto-measurement multi-device script file, measure noise from die-to-die, subdie-to-subdie and save the data to your directory automatically.




Figure 6: NoiseProPlus™ device window displaying multi-die noise data

Note that auto-measurement procedure is identical to the manual measurement steps except that the software internally loads a new script file for auto-measurement when wafer map information is available. NoiseProPlus™ creates multi-die noise data tabs under the folder specified in auto-measurement mode as shown in fig. 6 above. This multi-die data can then be super-imposed to visualize the across wafer noise variability.

© 2018 ProPlus Design Solutions, Inc. All rights reserved. Printed in the United States of America. ProPlus Design Solutions, Inc., 2025 Gateway Place, Suite 130, San Jose, CA 95110, USA.

Copyright: This publication is protected by copyright and any unauthorized use of this publication may violate copyright, trademark, and other laws. This document contains proprietary information and protected by copyright. No part of this document may be reproduced, copied, or translated in any form or any means without prior written permission from ProPlus. This statement grants you permission to print one (1) hard copy of this publication for internal business purposes only, provided that this entire notice appears in all copies. In duplicating any part of this document, the recipient agrees to make every reasonable effort to prevent the unauthorized use and distribution of the proprietary information.

Disclaimer: The information in this document is subject to change without prior notice. All trademarks and/or registered trademarks contains in this document are property of their respective owners. ProPlus makes no warranty, representation, or guarantee regarding the fitness of its products for any particular purpose and specifically disclaims any warranty of merchantability and any warranty of non-infringement. ProPlus does not assume any liability arising out of the application or use of any product, and specifically disclaims any and all liability, including without limitation, special, incidental or consequential damages.

Trademark: All trademarks are the property of their respective holders.

MPI Global Presence

Asia region: EMEA region:

Direct contact: ast-asia@mpi-corporation.com ast-europe@mpi-corporation.com America region: ast-americas@mpi-corporation.com

MPI global presence: for your local support, please find the right contact here: www.mpi-corporation.com/ast/support/local-support-worldwide

